

# Illustrated Parts List - IPL Update



Product Name(s)

**545FXT**

Description of change

New Throttle wire with lubrication nipple. To prevent wire from freezing. Wiring protection changed due to lubrication nipple.

Comments

Not backward compatible.  
On products produced before s/n 20152500060, throttle handle assy kit (ref no 40) and wiring assy kit (ref no 41) must be used.

Introduced from

Serial number / Date	Remark
20152500060	All parts below


IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle controls	35	577 00 03-05	Throttle handle assy	577 00 03-02	
Throttle controls	40	588 58 57-01	Throttle handle assy	-	<b>KIT</b>
Throttle controls	37	581 92 79-02	Wiring assy	525 43 75-02	
Throttle controls	41	588 58 59-01	Wiring assy	-	<b>KIT</b>
Fuel tank	2	584 14 81-01	Wiring protection	537 17 25-02	

Throttle handle assy:




577 00 03-02





577 00 03-05

# Illustrated Parts List - IPL Update

Wiring protection:



537 17 25-02



584 14 81-01