Illustrated Parts List - IPL Update



Product Name(s)

555FX

Description of change

- 1. New spare part Throttle handle assy
- 2. Change of material in Tube. New material has a higher tensile strength.
- 3. Removal of Hose clamp from the return fuel hose on carburettor because of assembly issues.
- 4. Change of screw for the retainer in Throttle handle assy with heat system.

Comments

Backward compatible

Introduced from

| Serial number / Date | Remark |
|----------------------|----------------------|
| 2017-05 | Throttle handle assy |
| 2016-04 | Tube |
| 2016-03 | Hose clamp |
| 2017-05 | Screw |

IPL updates

| Page title | Ref. | New part no | Name | Excl. part no. | Remark |
|-------------------------|------|--------------|----------------------|----------------|----------------|
| Throttle controls | 38 | 537 19 72-09 | Throttle handle assy | | New spare part |
| Shaft | 1 | 502 25 94-01 | Tube assy | 510 02 78-07 | |
| Carburetor & Air filter | 29 | | Hose clamp | 544 34 86-01 | Removed |
| Throttle controls | 23 | 503 21 66-74 | Screw IHSCT | 503 21 71-20 | |