

# Illustrated Parts List - IPL Update



Product Name(s)

**555FXT**

Description of change

New Throttle wire with lubrication nipple. To prevent wire from freezing. Wiring protection changed due to lubrication nipple.

Comments

Not backward compatible.  
On products produced before s/n 20152400010, wiring assy kit (ref no 35) must be used.

Introduced from

Serial number / Date	Remark
20152400010	All parts below

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle controls	38	581 53 63-02	Wiring assy	537 40 34-02	
Throttle controls	35	588 78 62-01	Wiring assy, kit	-	<b>KIT</b>
Fuel tank	14	581 75 53-01	Wiring protection	544 10 95-02	

Wiring protection:

