

Illustrated Parts List - IPL Update



Product Name(s)

535FBX

Description of change

1: Crankcase assy - Material changed from magnesium to aluminium to increase the strength
2: Clutch cover - Material changed from magnesium to aluminium to increase the strength
3: Screw - Changed due to new material in clutch cover

Comments

Crankcase assy and clutch cover are fully interchangeable.

When changing clutch cover type, screws must be changed:

Screw 725 53 29-56 for aluminium cover 574 84 29-01 (s/n from 20151500019)

Screw 503 21 74-16 for magnesium cover 537 30 29-01 (s/n up to – 20151500018)

Introduced from

Serial number / Date	Remark
s/n from 20151500019 -	Crankcase assy 585 38 22-01
s/n from 20151500019 -	Clutch cover 574 84 29-01
s/n from 20151500019 -	Screw 725 53 29-56

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Crankcase	9	585 38 22-01	Crankcase	544 03 89-01	
Clutch cover	13	574 84 29-01	Clutch cover assy	537 30 29-01	
Clutch cover	3	725 53 29-56	Screw IHSCM	503 21 74-16	