

# Illustrated Parts List - IPL Update



Product Name(s)

**555FRM**

Description of change

Removal of Hose clamp from the return fuel hose on carburettor because of assembly issues.

Comments

Backward compatible

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2016-03	Hose clamp

IPL updates

<b>Page title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Carburetor & Air filter	29		Hose clamp	544 34 86-01	Removed