

Illustrated Parts List - IPL Update



Product Name(s)

T540XP

Description of change

1. Filter holder assy; Improved filter compensation. 506 94 84-02.
2. Inlet pipe assy: The attachment of the suction hose 577 40 64 is improved with a new nipple on the inlet pipe, 525 39 68-02.
3. New screw, 577 40 12-02.
4. Rear anti vibration holder improved on cylinder cover, 516 03 46-02.
5. New fuel tank kit. Fixing of the wiring is improved and a new cable cover is included.

Comments

Old cable cover 522 62 09-01 does not fit in new fuel tank 522 59 02-02. (See new fuel tank ,kit 588 45 43-01.)
All other changes are Fully interchangeable.

Introduced from

| Serial number / Date | Remark |
|----------------------|--|
| S/n 20152300001 | Filter holder assy 506 94 84-02 |
| S/n 20152300001 | Inlet pipe assy 525 39 68 -02. |
| S/n 20150700001 | New screw 577 40 12-02. |
| S/n 20152300001 | Cylinder cover, 516 03 46-02. |
| S/n 20152300001 | Fuel tank, kit 588 45 43-01 (522 59 02-02 + 522 62 09-02). |

IPL updates

| Page Title | Ref. no | New part no | Name | Excl. part no. | Remark |
|-------------------------|---------|--------------|---------------------|----------------|--------|
| Carburetor & air filter | 7 | 506 94 84-02 | Filter holder assy | 506 94 84-01 | |
| Carburetor & air filter | 18 | 525 39 68-02 | Inlet pipe assy | 525 39 68-01 | |
| Carburetor & air filter | 24 | 577 40 12-02 | Screw ITXSCM | 577 40 12-01 | |
| Cylinder cover | 1 | 516 03 46-02 | Cylindercover assy. | 516 03 46-01 | |
| Cylinder & piston | 8 | 577 40 12-02 | Screw ITXSCM | 577 40 12-01 | |
| Fuel tank | 4 | 522 62 09-02 | Cable cover | 522 62 09-01 | |
| Fuel tank | 6 | 588 45 43-01 | Fuel tank, kit | 522 59 02-01 | |