

# Illustrated Parts List - IPL Update



Product Name(s)

**572XP/XPG**

Description of change

Change of Throttle cable assy.  
Reason: New wire length.

Comments

New article Throttle cable assy 576 16 28-02 fully interchangeable.


Introduced from

Serial number / Date	Remark
183900657 / 2018-09-27	THROTTLE CABLE ASSY 576 16 28-02

IPL updates

Page Title	Ref. No	New part no	Name	Excl. part no.	Remark
Fuel tank	4	576 16 28-02	THROTTLE CABLE ASSY	576 16 28-01	

## 1. Fuel tank



Changed Throttle cable assy to 576 16 28-02 (pos. 4).