

# Illustrated Parts List - IPL Update



Product Name(s)

**555**

Description of change

1. New Carburettor (EL49) and new throttle valve. Improved idling and acceleration.
2. New bellow (grommet) for the throttle cable assy. This to extend the life length for the cable assy.
3. New improved antivibration element in rear spring.

Comments

If a throttle valve is needed several variants will be available. Check the saws serial number.  
Antivibration element: Fully interchangeable.

Introduced from

Serial number / Date	Remark
20141400001	New bellow.
20142500001	EL49 Carburettor.
20142500001	Antivibration element.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburettor and airfilter	10	5791941-08	Carburettor	5791941-06	
Carburettor details	1	5791941-08	Carburettor	5791941-06	
	13	5839749-01	Valve (throttle)		For Carburettor 5791941-08 (EL49).
	13	5790591-01	Valve (throttle)		For Carburettor 5791941-06 (EL47). Corrected.
Crankcase	4	5815592-01	Bellow / Grommet	5370883-01	Remain as spare part.
Fuel tank	15	5863121-01	Antivibration element	5846470-01	

