

Illustrated Parts List - IPL Update



Product Name(s)

H555

Description of change

1. Ignition module, assy : 581 72 35-02 (Rv.44) was 581 72 35-01 (Rv.43).
(Ignition module 581 61 71-02 (Rv.44) was 581 61 71-01 (Rv.43)).

Software updated:
We have changed the Ignition module to secure spark at idling and high speed.
2. New improved Fuel tank ventilation 501 15 29-01 added on tank 575 38 22-05. Tank ventilation improved regarding higher opening pressure.
3. New Tank cap assy and gasket number due to change of supplier.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20171000283	Valid for Ignition module 581 72 35-02.
s/n 20164000001	Valid for new Fuel Tank ventilation 501 15 29-01.
s/n 20161100001	Valid for Tank cap assy. and gasket.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system	1	581 72 35-02	Ignition Module	581 72 35-01	
Fuel tank	5	501 15 29-01	Tank vent,assy	537 35 95-01	
	19	522 62 00-03	Tank cap, assy	522 62 00-01	
	20	589 24 11-01	Gasket	537 21 50-01	
Crankcase	26	522 62 00-03	Tank cap, assy	522 62 00-01	
	27	589 24 11-01	Gasket	537 21 50-01	