

Illustrated Parts List - IPL Update



Product Name(s)

H556

Description of change

1. A new Inlet pipe, assy 583 96 41-03/-04 have been introduced. The change has been made to ensure the assembly and to avoid leakage.
2. The New Carburetor, kit 501 46 33-06 consist of: New Carburetor ZAMA140059A, a separate support sleeve 582 02 51-01 and AT-instruction.
3. New article number and some minor changes on Air Nozzle due to change of supplier.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 2018 5100289	Valid for Carburetor Kit, Flange, Support sleeve and Inlet pipe assy.
s/n 20171700154	Valid for Air nozzle.


IPL updates

Page Title	Ref . no	New part no	Name	Excl. part no.	Remark
Carburetor Details	1	501 46 33-06	Carburetor, kit	501 46 33-04	
Carburetor & Air filter	10	501 46 33-06	Carburetor, kit	501 46 33-04	
	12	505 16 52-02	Flange	505 16 52-01	
	14	583 96 41-03	Inlet pipe	583 96 41-01	
	14	583 96 41-04	Inlet pipe	583 96 41-02	Cold resistant
	21	582 02 51-01	Support Sleeve		New Spare part.
Crankcase	24	588 06 55-01	Air nozzle	520 29 12-01	

Illustrated Parts List - IPL Update


1. Carburetor

New version



501 46 33-06, ZAMA140059A

Old version



501 46 33-04, ZAMA140056A

