

# Illustrated Parts List - IPL Update



Product Name(s)

**545 FXT**

Description of change

1. M6x65 replaces M6x60.
2. Protective cover has been removed from winter kit.
3. Screw and cooling air conductor are no longer included in starter kit, but as separate parts.

Comments

1. Fully interchangeable. For instructions, please see Service Bulletins.

Introduced from

Serial number / Date	Remark
2011-09	Screw 725 23 83-81
2014-01	Protective cover 575 94 80-01 removed
	Screw 573 99 43-04 and cooling air conductor 510 20 50-01 removed from starter kit.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle control	30	725 23 83-81	Screw EHHM	725 23 82-85	
Accessories			Protective cover	575 94 80-01	Removed
Starter	9		Screw IHSCFMO	573 99 43-04	Removed from starter kit
Starter	10		Cooling air conductor	510 20 50-01	Removed from starter kit