



IPL, Rotary Broom, 2004-03, 106 28 44-62


953 53 08-09, 953 53 09-01

Rotary Broom

Spare parts	Replaces	
Ersatzteile	Ersetzt	
Pièces détachées	Remplace	
Reserve onderdelen	Vervangt	
Repuestos	Reemplaza	
Reservdelar	Ersätter	106 28 44-61

A



1		2	
	531 01 21-63		535 41 48-51



PF=ProFlex 18/21
*compl 535 41 48-18


**xxx xx xx-xx = New part,
Neues teil,
Nouvelle piece,
Nueva pieza,
Ny detalj**

B



1


Kit of 31 pcs.
535 41 48-61



Correction:
531 41 48-51 535 41 48-51




535 43 74-01



xxx xx xx-xx = New part,
Neues teil,
Nouvelle piece,
Nueva pieza,
Ny detalj

C



D Accessories
Zubehöre
Accessoires
Acessorios
Tillbehör

*compl 535 41 48-25

*535 41 48-30

*535 41 48-49

*535 41 48-22

xxx xx xx-xx = New part,
Neues teil,
Nouvelle piece,
Nueva pieza,
Ny detalj

(x2) *~~531 01 34-70~~

~~531 01 34-79~~ (x2)