




IPL, LDX Blower Att., 2010-08, 545 10 34-55


LDX Blower Att.

Spare parts
Ersatzteile
Pièces détachées
Reserve onderdelen
Repuestos
Reservdelar

Parts List No. 545103455		UNIVERSAL PARTS LIST	MODEL LDX Blower Att.	
Date Replaces			EBX Blower Att.	
2/02/10	545103455 - 6/13/07	NOTE: Illustration may differ from actual model due to design changes.	Page: 1	

TYPE 1







AWARNING
All repairs, adjustments and maintenance not described in the Operator's Manual must be performed by Qualified Service Personnel.

Ref.	Part No.	Description	Ref.	Part No.	Description	
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.	530096026 530015814 530096042 530016389 530055123 530095892 530016273 530016179 530096025 545006081	Clamp - Right Screw Housing - Blower (Upper) Washer Impeller Arbor - Impeller Housing - Blower (Lower) Screw Screw Clamp - Left Kit - Lower Driveshaft (Incl. Flex)		Not 545002807	Shown Decal-Shaft Warning	

Parts List No. 545103455		UNIVERSAL PARTS LIST	MODEL LDX Blower Att.	
Date Replaces			EBX Blower Att.	
2/02/10	545103455 - 6/13/07	NOTE: Illustration may differ from actual model due to design changes.	Page: 2	





AWARNING
All repairs, adjustments and
maintenance not described in
the Operator's Manual must be
performed by Qualified Service
Personnel.

Ref.	Part No.	Description	Ref.	Part No.	Description
1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	530096026 530015814 530096042 530016389 530055123 530095892 530096273 530016273 530016179 530096025 545006081	Clamp - Right Screw Housing - Blower (Upper) Washer Impeller Arbor - Impeller Housing - Blower (Lower) Screw Screw Screw Clamp - Left Kit - Lower Driveshaft (Incl. Flex)		Not 545002807	Shown Decal-Shaft Warning