

# Illustrated Parts List - IPL Update



Product Name(s)

**525PT5S**

Description of change

1. A new sprocket system has been introduced as spare part. Old sprocket has been exchanged by a new sprocket and two bronze washers.
2. A new kit, ring 590 94 02-01, for locking device has been created, including previous separate articles ring 522 74 26-01 and nut 510 09 61-01. These two parts have been redesigned, with chamfers on both sides of the inner sleeve, and therefore needs to be changed at the same time.
3. Screw replacement in trigger. Screw with T27 head exchanges screw with inhex head.

Comments

Backward compatible

Introduced from

Serial number / Date	Remark

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Saw head	41	582 87 22-01	Sprocket	580 76 05-01	<b>New spare part kit 1/4"</b>
Saw head	41	582 87 22-02	Sprocket	580 10 00-01	<b>New spare part kit 3/8"</b>
Shaft	6	590 94 02-01	Ring	510 09 61-01 522 74 26-01	<b>New spare part kit</b>
Throttle controls	21	579 86 56-01	Screw ITXSCFM	503 20 16-02	