

Illustrated Parts List - IPL Update



Product Name(s)

555FX

Description of change

1.M6x65 replaces M6x60
2. Warning label updated

Comments

1. For instructions, please see Service Bulletins.
Both changes are fully interchangeable.

Introduced from

Serial number / Date	Remark
2011-09	Screw 725 23 83-81
2014-08	Label 587 11 34-04

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle control	33	725 23 83-81	Screw EHHM	725 23 82-85	
Shaft	5	587 11 34-04	Label	537 29 47-10	