

Illustrated Parts List - IPL Update



Product Name(s)

555FXT

Description of change

1. New spare parts - Throttle handle assy and Throttle handle assy kit.
2. Change of material in Tube. New material has a higher tensile strength.
3. Removal of Hose clamp from the return fuel hose on carburettor because of assembly issues.
4. Change of screw for the retainer in Throttle handle assy with heat system.

Comments

Backward compatible

Introduced from

Serial number / Date	Remark
2017-06	Throttle handle assy, Throttle handle assy kit
2016-04	Tube
2016-03	Hose clamp
2017-05	Screw

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle controls	39	590 84 00-01	Throttle handle assy, kit		New spare part
Throttle controls	40	537 19 72-15	Throttle handle assy		New spare part
Shaft	1	502 25 94-01	Tube assy	510 02 78-07	
Carburetor & Air filter	29		Hose clamp	544 34 86-01	Removed
Throttle controls	23	503 21 66-74	Screw IHSCT	503 21 71-20	