

# Illustrated Parts List - IPL Update



Product Name(s)

**545RX**

Description of change

1. Change of alloy in tube assy.
2. Changed ignition module for better product performance

Comments

Both changes are backward compatible.

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2016-05	Tube assy and ignition system

IPL updates

<b>Page title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Shaft	1	586 26 26-02	Tube assy	577 26 21-04	<b>Backward compatible</b>
Ignition system	1	585 07 39-04	Ignition system	585 07 39-01	<b>Backward compatible</b>