

Illustrated Parts List - IPL Update



Product Name(s)

135R, 336FR, 336FRD/336RK, BC2235, CC2235

Description of change

The crankcase for the affected models should be in aluminium. The present spare part is in magnesium.

Introduced from	Serial number / Date 2014-06-10	Product
-----------------	------------------------------------	---------

Page Title	Ref. no	New part no	Name	Action	Excl. part no.	Remark
CRANKCASE	1	585 38 22-01	CRANKCASE ASSY	Replace	544 03 89-01	
SHORT BLOCK	1	585 38 23-01	SHORT BLOCK	Replace	576 79 68-01	
					
					

Comments