

Illustrated Parts List - IPL Update



Product Name(s)

545FX AT

Description of change

New spare part to be used to keep the ignition cable from getting in contact with the cylinder cooling flanges, to avoid wear of the ignition cable.

Comments

Introduced from

Serial number / Date	Remark

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system	2	593 24 70-01	Cable guide		New spare part