

# Illustrated Parts List - IPL Update



Product Name(s)

**555FRM**

Description of change

1.M6x65 replaces M6x60  
2. Warning label updated

Comments

1. For instructions, please see Service Bulletins.  
Both changes are fully interchangeable.

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2011-09	Screw 725 23 83-81
2014-08	Label 587 11 34-04

IPL updates

<b>Page Title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Throttle control	20	725 23 83-81	Screw EHHM	725 23 82-85	
Shaft	5	587 11 34-04	Label	537 29 47-10	