

Illustrated Parts List - IPL Update



Product Name(s)

535RJ

Description of change

1. The cylinder gasket has been changed. Three bulges have been added to help keeping the gasket in place while assembling the cylinder.
2. Change of material in antivibration element. Keeps the tower steady even in wet conditions.

Comments

Both changes are backward compatible

Introduced from

Serial number / Date	Remark
2016-04	537 33 30-02
2016-04	537 34 89-01

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder piston	7	537 33 30-02	Gasket	537 33 30-01	
Tower	9	537 34 89-03	Antivibration element	537 34 89-01	