

Illustrated Parts List - IPL Update



Product Name(s)

H545/G MarkII

Description of change

1. We have implemented a new separate Protective cap 596 91 13-01 to prevent dirt from getting into the ball bearing/crankcase.
2. Protective cap 596 91 13-01 and sleeve 589 33 13-01 added in Crankcase kit 595 89 77-01.

Comments

This update is fully exchangeable.


Introduced from

Serial number / Date	Remark
s/n 20201700261	Valid for protective cap 596 91 13-01.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Crankcase	31	596 91 13-01	Protective Cap		New spare part.

1. Protective cap



596 91 13-01