

Illustrated Parts List - IPL Update



Product Name(s)

372 XP X-Torq

Description of change

1. Brake Spring changed to a stronger variant.
2. Clutch Drum get new part number.
3. Screw for Ignition Module changed for better grip.
4. Nut for flywheel changed to avoid for high torque.
5. Washer added to flywheel to avoid for high torque.
6. Screw had wrong quantity in list.

Comments

All updates are fully interchangeable

Introduced from

Serial number / Date	Remark
20144500001-	Brake Spring 503 70 99-02
20144400769-	Clutch Drum 586 98 06-01
20144400769-	Clutch Drum 586 98 06-02
20150700769-	Screw lhscm 586 28 93-01
20151100001-	Nut 503 22 10-11
20151100001-	Washer 503 23 01-01
20151100001-	Screw 725 53 29-56

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Chain Brake	6	503 70 99-02	Brake Spring	503 70 99-01	
Clutch & Oil Pump	17	586 98 06-01	Clutch Drum	503 93 24-71	
Clutch & Oil Pump	17	586 98 06-02	Clutch Drum	503 93 24-72	
Ignition System	15	586 28 93-01	Screw lhscm	503 20 02-20	
Ignition System	24	503 22 10-11	Nut	503 22 04-01	
Ignition System	25	503 23 01-01	Washer		
Clutch & Oil Pump	10	725 53 29-56	Screw		Changed from 1-2 pcs