

# Illustrated Parts List - IPL Update



Husqvarna  
Group

Product Name(s)

2014-04-28

560XP, 560XPG

Description of change

1. New Carburettor (EL48) and new throttle valve. Improved idling and acceleration.
2. New bellow (grommet) for the throttle cable assy. This to extend the life length for the cable assy

Comments

When need a new Carburettor the new one has replaced the old one.  
If a throttle valve is needed several variants will be available. Check the saws serial number.

Introduced from

Serial number / Date	Remark
20141400001	EL48 Carburettor and new bellow.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburettor and airfilter	10	5791941-07	Carburettor	5791941-05	
Carburettor details	1	5791941-07	Carburettor	5791941-05	
	13	5839747-01	Valve (throttle)		For Carburettor 5791941-07 (EL48).
	13	5781762-01	Valve (throttle)		For Carburettor 5791941-05 (EL46). Corrected.
Crankcase	4	5815592-01	Bellow / Grommet	5370883-01	Remain as spare part.