

Illustrated Parts List - IPL Update



Product Name(s)

455 Rancher

Description of change

1. A new Oil hose has been introduced in production. A better supply of oil to the oil pump.
2. Correction. New part number for the clutch drum.
3. A new Rear handle assy has been introduced in production. A better strength because a better material is used.
4. A new Cap has been introduced in production. A better strength because a better material is used.
5. Correction. New part number for the throttle trigger.
6. Correction. New part number for the impuls hose.
7. Correction. New part number for the starter screw.

Introduced from	Serial number / Date	Product
Oil hose	20121800002	455 Rancher
Rear handle assy	20123800001	455 Rancher
Cap	20123800001	455 Rancher

Page Title	Ref. no	New part no	Name	Action	Excl. part no.	Remark
Clutch & Oil pump	15	5372614-02	Oil hose	Replaced by	5372614-01	See service bulletin
	3	5372916-04	Clutch drum	Replaced by	5372916-02	
Handle & Controls	5	5809459-01	Rear handle assy	Replaced by	5742118-01	
	17	5372307-04	Cap	Replaced by	5372307-03	
	4	5372605-03	Throttle trigger	Replaced by	5372605-01	
Carburetor & air filter	17	5034006-10	Impulse hose	Replaced by	5443249-26	
Starter	10	5032173-21	Screw	Replaced by	5032173-72	

Comments

All these changes are interchangeable.

2013-01