

Illustrated Parts List - IPL Update



Product Name(s)

439

Description of change

Change the INLET PIPE

1. Improve hot restart
2. Improve strength
3. Improve unstable engine speed
4. Reduce sealant (liquid gasket) area

Comments

Introduced from

Serial number / Date	Remark
s/n 20174300651	Valid for new INLET PIPE

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
G CARBURETOR & AIR FILTER	9	587 13 94-01	INLET PIPE	573 95 44-01	