

Illustrated Parts List - IPL Update



Product Name(s)

272 XP

Description of change

1. New carburettor with updated throttle valve.
2. Change due to delivery problem.
3. New supplier, exactly the same ignition module as before.
4. New material in fuel hose.
5. New supplier and updated detail drawing.
6. New screw.
7. Improved durability.
8. New ring.

Comments

Fully interchangeable

Introduced from

Serial number / Date	Remark
20101410613 -	Carburettor 574 33 16-01
20134600001 -	Needle bearing 577 57 24-01
20160500001 -	Ignition module 587 32 96-01
20132300001 -	Fuel hose 581 75 62-01
20051800001 -	Screw IHSCFT 503 21 49-72
20051800001 -	Screw IHSCM 503 20 02-10
20051800001 -	Ball bearing 544 06 86-01
	Ring 503 79 95-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburettor and air filter	13	574 33 16-01	Carburettor	503 28 03-16	
Carburettor details	1	574 33 16-01	Carburettor	503 28 03-16	
Crankshaft	3	577 57 24-01	Needle bearing	503 73 39-01	Remain as spare part.
Cylinder and piston	11	577 57 24-01	Needle bearing	503 73 39-01	Remain as spare part.
Electrical	9	587 32 96-01	Ignition module	544 01 84-01	
Handle and controls	15	581 75 62-01	Fuel hose	544 32 50-01	
Starter	2	503 21 49-72	Screw IHSCFT	503 21 49-16	Remain as spare part
Muffler	7	503 20 02-10	Screw IHSCM	503 20 07-10	Remain as spare part
Crankshaft	2	544 06 86-01	Ball bearing	738 22 02-05	
Carburettor details	26	503 79 95-01	Ring	505 31 67-36	
Cylinder piston	-	503 51 99-01	Heat deflector	-	Added to IPL