

Illustrated Parts List - IPL Update



Product Name(s)

H61

Description of change

1. New supplier, exactly the same ignition module as before.
2. New material in fuel hose.
3. New supplier and updated detail drawing.
4. Improved durability.
5. New ring.
6. Change due to delivery problem.

Comments

Fully interchangeable

Introduced from

Serial number / Date	Remark
20160500001 -	Ignition module 587 32 96-01
20132300001 -	Fuel hose 581 75 62-01
20051800001 -	Screw IHSCT 503 21 49-72
20051800001 -	Ball bearing 544 06 86-01
	Ring 503 79 95-01
20134600001 -	Needle bearing 577 57 24-01

IPL updates

Page Title	Ref. no.	New part no	Name	Excl. part no.	Remark
Electrical	9	587 32 96-01	Ignition module	544 01 84-01	New name: Ignition module
Handle and controls	15	581 75 62-01	Fuel hose	544 32 50-01	
Starter	2	503 21 49-72	Screw IHSCT	503 21 49-16	Remain as spare part.
Crankshaft	2	544 06 86-01	Ball bearing	738 22 02-05	
Carburettor details	26	503 79 95-01	Ring	505 31 67-36	
Crankshaft	3	577 57 24-01	Needle bearing	503 73 39-01	Remain as spare part.
Cylinder piston	10	577 57 24-01	Needle bearing	503 73 39-01	Remain as spare part.