

Illustrated Parts List - IPL Update



Husqvarna
Group

EM-OSUC/AIf_2019-04-11

Product Name(s)

T540XP II

Description of change

T540XP II_2019-04 red

#1. Page crankcase:

Pos 23: Spring Pin 501 62 33-01 added.

#2. Page Ignition system:

Pos 1: Ignition module (Walbro) 587 30 68-04 was 587 30 68-03.

#3. Page Carburettor & air filter:

Pos 9: Carburettor 591 49 53-01 (Walbro AT-14) was 588 04 41-01 (Walbro AT-11).

#4. Page Carburettor:

Pos 18: Repair kit 597 79 97-01 was 580 69 99-01.

#5. Page Carburettor:

Pos 20: Gasket kit 597 79 98-01 was 580 70 00-01.

Comments

The products goes slightly smoother / cleaner at high speed.
This due to new carburettor (AT-14) and new Ignition Module.

Introduced from

Serial number / Date	Remark
From production start	Spring Pin 501 62 33-01
s/n 2019 12 00576	Ignition module 587 30 68-04
s/n 2019 05 00001	Carburettor 591 49 53-01
s/n 2019 17 00001	Repair kit 597 79 97-01
s/n 2019 17 00001	Gasket kit 597 79 98-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Page H Crankcase	Pos 23	501 62 33-01	Spring Pin		Picture changed. Article added to the page.
Page M Ignition M	Pos 1	587 30 68-04	Ignition module	587 30 68-03	
Page G Carb & air	Pos 9	591 49 53-01	Carburettor	588 04 41-01	Walbro AT-14
Page P Carburettor	Pos 18	597 79 97-01	Repair kit	580 69 99-01	
Page P Carburettor	Pos 20	597 79 98-01	Gasket kit	580 70 00-01	