

Illustrated Parts List - IPL Update



Product Name(s)

T540XP11

Description of change

1. New improved Fuel tank ventilation 501 15 29-02 added on tank 522 59 02-04. Tank ventilation improved regarding higher opening pressure and Fuel Tank has been reinforced where the rear antivibration elements is attached.
2. Rear antivibration element changed to barrel-shaped spring 588 69 22-01, to improve the durability.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20154800402	Valid for new Fuel Tank ventilation 501 15 29-02 and Tank 522 59 02-04.
s/n 20160800001	Valid for Antivibration element 588 69 22-01.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Fuel tank	6	522 59 02-04	Fuel tank	522 59 02-02	
	7	501 15 29-02	Tank vent, assy	537 35 95-01	Remain as spare part.
	14	588 69 22-01	Antivibration element	510 07 11-01	

2. Antivibration element.



588 69 22-01



510 07 11-01