

Illustrated Parts List - IPL Update



Product Name(s)

T540XP II

Description of change

1. A new Piston assy 586 44 62-04 and Piston ring 593 64 49-01 have been introduced. The change has been made to improve engine durability and start ability.
2. New article number for Cylinder assy due to new Piston assy.
3. Old Piston ring 577 96 05-01 will remain as spare part for Piston 586 44 62-02.

Comments

This update is fully exchangeable regarding Cylinder assy and Piston assy. Piston ring is **not** exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20201400192	Valid for Piston assy 586 44 62-04 and Piston ring 593 64 49-01 .

IPL updates


Page Title	Ref . no	New part no	Name	Excl. part no.	Remark
Cylinder & Piston	1	586 34 15-02	Cylinder assy	576 67 62-02	
	2	586 44 62-04	Piston assy	586 44 62-02	
	4	593 64 49-01	Piston ring MC25 HKB		New Spare part.

Illustrated Parts List - IPL Update

1. Piston ring, marking.

New version

Old version



Marked with:



593 64 49-01 MC25 HKB

577 96 05-01 