

Illustrated Parts List - IPL Update



Product Name(s)

Husqvarna 435e II

Description of change

1. We have improved Starter Pulley Kit 586 65 96-03. The pulley and driver has been improved due to issues with the assisting spring slipping when pulling the rope.

Comments

This update is fully exchangeable. **Note:** Starter Pulley Kit 586 65 96-03 cannot be mixed with subcomponents in Starter Pulley Kit 586 65 96-02.

Introduced from

Serial number / Date	Remark
s/n 20190800634	Valid for Starter Assy, 579 42 54-06. North America
s/n 20190600288	Valid for Starter Assy, 579 42 54-06. RoW
s/n 20194800634	Valid for Starter Pulley, Kit 586 65 96-03. North America
s/n 20190600288	Valid for Starter Pulley, Kit 586 65 96-03. RoW

IPL updates

Page Title	Ref no	New part no	Name	Excl. part no.	Remark
Starter	1	579 42 54-06	Starter Assy	579 42 54-04	
	15	586 65 96-03	Starter Pulley Kit	586 65 96-02	