

Illustrated Parts List - IPL Update



Product Name(s)

525 HF3S

Description of change

1. Line was mistakenly pointing at Ignition Module 585 50 87-01 in the image.
Pos 2 is Ignition Cable spare part 584 82 66-01.
2. Spark Plug Cap updated regarding material.

Comments

Fully exchangeable

Introduced from

Serial number / Date	Remark
	Ignition cable 584 82 66-01
	Spark plug cap 586 10 72-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system and clutch	2	584 82 66-01	Ignition cable	585 50 87-01	
Ignition system and clutch	4	586 10 72-01	Spark plug cap	576 40 40-01	