

Illustrated Parts List - IPL Update



Product Name(s)

525LST

Description of change

1. Improved vibration isolation in Throttle control. New damper and retainer.
2. Reduce complexity and optimize the range of spare parts

Comments

1. Throttle control assy ref. 1 (578 27 95-03) is backward interchangeable. Damper ref. 11 (590 04 21-01) and retainer ref. 13 (589 63 85-01) needs to be replaced together.
2. See below

Introduced from

Serial number / Date	Remark
2018-06	All parts below

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle control	1	578 27 95-03	THROTTLE CONTROL	578 27 95-01	LS, LST
Throttle control	11	590 04 21-01	DAMPER	544 10 17-03	LS, LST
Throttle control	13	589 63 85-01	RETAINER	544 11 21-01	LS, LST
Accessories	9		TRIMMER GUARD ASSY	588 11 78-01	
Accessories	14		COMBINATIO N GUARD	501 13 67-05	
Accessories	18	501 13 67-05	GUARD	501 13 69-02	
Accessories	22		PLATE	526 05 66-01	