

Illustrated Parts List - IPL Update



Product Name(s)

H565

Description of change

1. Minor correction, updated number on Flywheel Assy to 576 77 72-01.
2. We have implemented a new Ignition Module 582 10 50-02 with new software to improve startability.

Comments

This update is fully exchangeable.

Introduced from

| Serial number / Date | Remark |
|----------------------|---|
| s/n 20191900001 | Valid for Flywheel assy 576 77 72-01. |
| s/n 20200600189 | Valid for Ignition Module 582 10 50-02. |
| | |

IPL updates

| Page Title | Ref. No | New part no | Name | Excl. part no. | Remark |
|-----------------|---------|--------------|-----------------|----------------|--------|
| Ignition system | 1 | 576 77 72-01 | Flywheel assy | 590 28 12-01 | |
| | 4 | 582 10 50-02 | Ignition Module | 582 10 50-01 | |
| | | | | | |
| | | | | | |
| | | | | | |