

Illustrated part list IPL update

Instruction

Husqvarna Division; Handheld

Husqvarna



Product Name(s)

320iB

Description of change

1. Extended pull rod for better functionality.
2. Improved serviceability, the fan system will be offered as a complete assembly instead of several individual components. This is a step to align all battery blowers' IPLs.

Comments

1. IPL update_320ib_Tube_2020-11 was incorrect and this update is a correction.
2. Fully interchangeable.

Introduced from

Serial number / Date	Remark
2021-02	

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
TUBE	4	582 37 09-01	Pull rod	582 37 09-02	See Service bulletin B1201029A-07
FAN	1	529 99 66-01	Motor assy	582 31 34-01 584 15 12-02 582 07 91-01 503 20 25-12 581 55 12-01 589 58 96-01 589 59 02-01	