

Illustrated Parts List - IPL Update



Product Name(s)

578BTF Blower (967307702)

Description of change

Optimized blow pipe and change pipe end to metal.
Improved handle lever side mounted changed to top mounted.

Comments

The new solution is not backward compatible.
On products produced before s/n 2018-11 the 596397201 Pipe kit (ref. 10) must be used, see image.

Introduced from

Serial number / Date	Remark
2018-11	All parts below

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
HARNESS	2	594992101	BAND	511802901	s/n from – 2018-11
THROTTLE CONTROLS	19		SQUARE NUT	503226501	
THROTTLE CONTROLS	20		HOLDER	502245301	
THROTTLE CONTROLS	21		HANDLE HOLDER	576579701	
THROTTLE CONTROLS	22		TURNING KNOB	504800301	
THROTTLE CONTROLS	23		SCREW EHHM	725234451	
THROTTLE CONTROLS	28	596391801	LEVER	576579601	s/n from – 2018-11
THROTTLE CONTROLS	29		RING	586894701	
TUBE	1	595005701	END PIPE ASSY	586894601	s/n from – 2018-11
TUBE	2	594103101	PIPE	576581701	s/n from – 2018-11
TUBE	3	576564801	PIPE	576581401	s/n from – 2018-11
TUBE	6	544276001	CLAMP	502842801	s/n from – 2018-11
TUBE	9	596473501	HOLDER KIT		s/n from – 2018-11
TUBE	10	596397201	PIPE KIT		s/n up to – 2018-11

Illustrated Parts List - IPL Update



Husqvarna
Group

