

# Illustrated Parts List - IPL Update



Product Name(s)

**H450 II**

*Description of change*

1. Updated Oil Hose 544 08 42-02 added. Sealing knob removed to simplify assembly.
2. Number change due to a durability update on Ignition Module to 579 63 88-05.

*Comment*

These changes are fully exchangeable.

*Introduced from*

Serial number / Date	Remark
S/n 20201500384	Valid for Oil hose, 544 08 42-02. For RoW.
S/n 20202500001	Valid for Oil hose, 544 08 42-02. For North America.
S/n 20203401344	Valid for Ignition Module 579 63 88-05 (MBU-052C).



*IPL updates*

Page Title	Ref. no	New part no.	Name	Excl. part no.	Remark
Clutch & Oil pump	8	544 08 42-02	Oil hose	544 08 42-01	
Ignition system	7	579 63 88-05	Ignition module	579 63 88-03	

1. Oil hose

New version

Old version



544 08 42-02

544 08 42-01

## 2. Ignition Module

New version

Marking:

<b>579 63 88-05</b>
<b>MBU – 052C</b>

579 63 88-05

Old version

Marking:

<b>579 63 88-03</b>
<b>MBU – 052A</b>

579 63 88-03

