Illustrated Parts List - IPL Update

Product Name(s)

H455RII

Description of change

- 1. New Ignition module, assy : 586 81 50-02 was 575 67 37-02. Minor correction.
- 2. New improved Fuel tank ventilation 501 15 29-01 added on crankcase 577 59 54-03. Tank ventilation improved regarding higher opening pressure.
- 3. Crankshaft assy. 537 31 40-03 was -02. Correction.
- 4. New Tank cap assy and gasket number due to change of supplier. Minor correction.
- 5. Choke control changed to secure correct assembly.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20154400001	Choke control assy.
s/n 20164400001	Crankcase and fuel ventilation.

IPL updates						
Page Title	Ref. no	New part no	Name	Excl. part no.	Remark	
Carburetor & air filter	1	510 01 72-02	Choke control assy.	510 01 72-01		
Crankcase	15	501 15 29-01	Tank vent assy	537 35 95-01		
	19	577 59 54-03	Crankcase	577 59 54-01		
Crankshaft	1	537 31 40-03	Crankshaft assy.	537 31 40-02	Correction.	
Fuel tank	7	522 62 00-03	Tank cap assy.	522 62 00-01	Minor correction.	
	9	589 24 11-01	Gasket	537 21 50-01	Minor correction.	
Ignition system	6	586 81 50-02	Ignition module	575 67 37-02	Minor correction.	



Illustrated Parts List - IPL Update

5. Choke control

New version









510 01 72-02

510 01 72-01

