

# Illustrated Parts List - IPL Update



Product Name(s)

**H550iBTX**

Description of change

New bumper design. The new one is only one piece and the old remains for detailed serial number below.

Comments

Note: You can't mix old and new bumpers. Change both bumpers at the same time. SKU and serial number reference for each bumper:

- 591458501 > 967681104 up to Serial Number 20230700257, 967681103 up to 20230700120, 967681105 up to 20225000321
- 591458201 > 967681104 up to Serial Number 20230700257, 967681103 up to 20230700120, 967681105 up to 20225000321
- 531017901 > 967681104 from Serial Number 20230700258, 967681103 from S/N 20230800175
- 531016901 > 967681104 from Serial Number 20230700258, 967681103 from S/N 20230800175

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
See above	

IPL updates

<b>Page title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Housing	15	531 01 79-01	Left bumper frame assy		Old bumpers ref.no. 14, 15 and 16 will remain as spare parts.
	12	531 01 69-01	Right bumper frame assy		Old bumpers ref.no. 11, 12 and 13 will remain as spare parts.