

Illustrated part list IPL update

Instruction

Handheld; Husqvarna Forest & Garden

Husqvarna



Product Name(s)

T540iXP, T540iXP Bluetooth, T540iXPG

Description of change

Improvement of chassis and the microswitch position.

The microswitch holder is adjusted to prevent it from sliding too far down in its seat. This can cause the trigger to remain in released position and the chainsaw will incorrectly act as if the brake is activated and will not be able to run.

Comments

Fully interchangeable.

Introduced from

Serial number / Date	Remark
November 25, 2022	Start of production

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Chassis	2	593 04 83-02	Chassis	593 04 83-01	