

Illustrated Parts List - IPL Update



Product Name(s)

550iBTX, 550iBTX BT

Description of change

New spare part kit is needed for PNC 967 68 11-01/-02 since old motor 593 59 10-01 is not produced anymore.
 SP kit is needed if customers with PNC 967 68 11-01/-02 wants to replace Motor assy 597 11 03-02

Comments

New motor 597 21 35-01 is not compatible with old CU 593 75 92-01

Introduced from

Serial number / Date	Remark
?	-

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Fan	2	547 30 65-01	Motor assy KIT	597 11 03-02	PNC 967681101, 967681102