

Illustrated Parts List - IPL Update



Product Name(s)

390 XP

Description of change

1. Brake Spring changed to a stronger variant.
2. Nut for flywheel changed to avoid for high torque.
3. Screw for Ignition Module changed for better grip.
4. Washer added to flywheel to avoid for high torque.
5. Ball Bearing changed article number.

Comments

All updates are fully interchangeable

Introduced from

Serial number / Date	Remark
20144500001-	Brake Spring 503 70 99-02
20151100001-	Nut 503 22 10-11
20150700769-	Screw lhscm 586 28 93-01
20151100001-	Washer 503 08 52-01
20151100001-	Ball Bearing 503 25 13-02

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Chain Brake & Clutch Cover	5	503 70 99-02	Brake Spring	503 70 99-01	
Ignition System	6	503 22 10-11	Nut	503 22 04-01	
Ignition System	7	586 28 93-01	Screw lhscm	503 20 02-20	
Ignition System	30	503 08 52-01	Washer		
Crank Shaft	4	503 25 13-02	Ball Bearing	503 25 13-01	