



505 56 88-07

Row Crop Cultivator (45-02641)



REPAIR PARTS FOR MODEL 45-02641 - ROW CROP CULTIVATOR



REF. NO.	PART NO.	QTY.	DESCRIPTION
1	63656	1	Hitch Ass'y.
2	64279	1	Frame Assembly
3	43022	7	Cultivator Tang
4	24238	2	Depth Gauge Bar
5	43432	5	Hex Bolt, 3/8-16 x 2-1/2" Lg.
6	HA21362	23	Nylock Nut, 3/8-16 Thread
7	46853	9	U-Bolt, 3/8-16 Thread
8	43070	10	Flat Washer, 3/8" Std. Wrt.
	48284	1	Owners Manual



Please do not return this product to the Store

For Missing Parts Or Questions on How to Assemble:

1. Call Agri-Fab at 1-800-448-9282 Option # 1
Monday through Friday, 7 am to 5 pm CST
2. Fax Agri-Fab at 217-728-2032 or email info@agri-fab.com

Missing part shipments are normally shipped from the Agri-Fab factory within 24 hours zip code 61951. 1 to 5 days delivery for UPS.

For Replacement and/or Repair Parts:

1. Call Agri-Fab at 1-800-448-9282 Option # 1
Monday through Friday, 7 am to 5 pm CST
2. Visit Agri-Fab's website at <http://www.agri-fab.com> and view illustrated parts breakdowns and parts listing and purchase parts via our <http://www.speedepart.com> site online.