




IPL, LDX Cultivator Att., 2010-08, 545 01 43-99

LDX Cultivator Att.

Spare parts
Ersatzteile
Pièces détachées
Reserve onderdelen
Repuestos
Reservdelar


Parts List No. 545014399		UNIVERSAL PARTS LIST	MODEL LDX Cultivator Att.	
Date Replaced			LDA Cultivator Att.	
8/04/11	545014399 - 2/02/10	NOTE: Illustration may differ from actual model due to design changes.	Page: 1	



AWARNING
All repairs, adjustments and maintenance not described in the Operator's Manual must be performed by Qualified Service Personnel.

Ref.	Part No.	Description	Ref.	Part No.	Description
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12.	530016363 530016362 545141901 530015515 530015209 530095987 530016364 530095986 530015209 530016366 530071479 545006080	Retainer - Hairpin Pin - Clevis Assy-Gearbox Locknut Washer - Flat Tine - Right Outside / Left Inside Washer - Felt Tine - Left Outside / Right Inside Washer - Flat Bolt - Washer Head Kit - Blade Guard Kit - Driveshaft Assy. (Incl. flex.)		545002805	Decal-Shaft Warning

Parts List No. 545014399		UNIVERSAL PARTS LIST	MODEL LDX Cultivator Att.	
Date Replaced			EDA Gallivator Att:	
8/04/11	545014399 - 2/02/10	NOTE: Illustration may differ from actual model due to design changes.	Page: 2	



All repairs, adjustments and maintenance not described in the Operator's Manual must be performed by Qualified Service Personnel.

Ref.	Part No.	Description	Ref.	Part No.	Description
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11.	530016363 530016362 545141901 530015515 530015209 530095987 530016364 530095986 530015209 530016366 530071479 545006080	Retainer - Hairpin Pin - Clevis Assy-Gearbox Locknut Washer - Flat Tine - Right Outside / Left Inside Washer - Felt Tine - Left Outside / Right Inside Washer - Flat Bolt - Washer Head Kit - Blade Guard Kit - Driveshaft Assy. (Incl. flex.)	r	~ 578667001	Decal-Shaft Warning