

Illustrated Parts List - IPL Update



Product Name(s)

555RXT

Description of change

Removal of Hose clamp from the return fuel hose on carburettor because of assembly issues.

Comments

Backward compatible

Introduced from

Serial number / Date	Remark
2016-03	Hose clamp

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburetor & Air filter	29		Hose clamp	544 34 86-01	Removed