

Illustrated Parts List - IPL Update



Product Name(s)

545RX

Description of change

1. Screw was changed for a better fixation of the blade.
2. New length of fuel hose. 38 mm instead of 39 mm.

Comments

Both changes are backward compatible.

Introduced from

| Serial number / Date | Remark |
|-----------------------------|---------------|
| 2017-04 | Screw |
| 2016-05 | Fuel hose |

IPL updates

| Page title | Ref. no | New part no | Name | Excl. part no. | Remark |
|-------------------------|----------------|--------------------|--------------|-----------------------|---------------|
| Accessories | 3 | 503 21 75-72 | Screw IHSCFT | 503 21 07-16 | |
| Carburetor & Air filter | 14 | 581 75 61-43 | Fuel hose | 581 75 61-40 | |