

# Illustrated Parts List - IPL Update



Product Name(s)

**336RK**

Description of change

Insulation wall changed to increase the air flow from flywheel.

Comments

Backward compatible

Introduced from

<b>Serial number / Date</b>	<b>Remark</b>
2017-01	

IPL updates

<b>Page title</b>	<b>Ref. no</b>	<b>New part no</b>	<b>Name</b>	<b>Excl. part no.</b>	<b>Remark</b>
Carburetor & Air filter	2	537 37 12-02	Insulation wall	537 37 12-01	