

# Illustrated Parts List - IPL Update



Product Name(s)

**555FRM**

Description of change

1. Handlebar brackets will no longer be available separately, only as a kit. Two kits have been created, composed of 2x screws, 1x upper bracket, 1x lower bracket. One kit according to service bulletin (see comment below), one kit for standard handlebar system.
2. Bevel gear - Threaded part of the blade shaft has been made 1,3mm longer than previous version.

Comments

1. 595 30 36 only to be used for products produced from s/n 20173300001 to s/n 20181100180.
2. Fully interchangeable.

Introduced from

Serial number / Date	Remark
See "comments".	Handlebar bracket
2018-04	Bevel gear

IPL updates

Page title	Ref. no	New part no	Name	Excl. part no.	Remark
Throttle controls	18	595 30 36-01	Handlebar bracket		See service bulletin
Throttle controls	18	595 53 36-01	Handlebar bracket	537 12 90-01 537 12 91-01 503 20 02-78	Standard handlebar system
Bevel gear	1	537 42 87-07	Bevel gear	537 42 87-05	