

Illustrated Parts List - IPL Update



Product Name(s)

H550XP/XPG

Description of change

1. Cylinder cover, assy 587 24 86-03 was 587 24 86-01. One hole added and a wall has been partly cut in order to improve the air flow for increased cooling of the engine.
2. New Crankshaft 577 76 73-07 with improved grip. New ball bearings and needle bearing.
3. New Ball bearings 525 43 42-02 and 505 13 35-02.
4. New Needle bearing 503 25 63-02.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20154800241	Cylinder cover.
s/n 20154500097	Valid for Bearings and Crankshaft.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder Cover	1	587 24 86-03	Cylinder Cover, assy	587 24 86-01	
Cylinder Piston	11	503 25 63-02	Needle bearing	503 25 63-01	
Crankshaft	1	577 76 73-07	Crankshaft assy	577 76 73-03	
	2	505 13 35-02	Ball bearing	505 13 35-01	
	3	525 43 42-02	Ball bearing	525 43 42-01	Remain as spare part.
	4	503 25 63-02	Needle bearing	501 45 16-01	Remain as spare part.

1. Cylinder cover, hole added.

